

Purpose	s47E(d)	Detection of undeclared asbestos
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	04JAN2018
	This report	05JAN2018
Location	Goods are currently at: s47E(d)	
Summary	<p>On 15DEC2017, a consignment of goods, including one IRON VESPA SIDECON and one IRON VESPA SPRINT, was imported from Indonesia. s47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in front drum brake linings from both Vespa's.</p> <p>Consignment details: Importer: s47F Consignor: s47G FID: AC3JAT49G Container: MRKU6968467 OBL: 962630144</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized s47E(d) CCB to consider s47E(d). 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> BIMS: xxxx-2018 NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Senior Border Force Officer, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Drafted by	Name: s22(1)(a)(ii) Position: Senior Border Force Officer, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Cleared by	Name: s22(1)(a)(ii) Position: Superintendent National Compliance Program Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	

Purpose	DETECTION OF UNDECLARED ASBESTOS	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	04JAN2018
	This report	05JAN2018
Location	Goods are currently at the importer's premise: §47E(d)	
Summary	<p>On 02DEC2017 two containers of goods declared as a PREFABRICATED HOUSE were imported from China by §47G.</p> <p>§47E(d)</p> <p>§47E(d) The importer was unable to provide appropriate assurances that the goods did not contain asbestos and was directed to arrange testing.</p> <p>On 03JAN2018 a hygienist examined house and took samples from the walls and floor.</p> <p>On 04JAN2018 test results were received confirming chrysotile asbestos in the flooring.</p> <p>Consignment Details: Consignee: §47G</p> <p>Consignor: §47G</p> <p>Container #: CYMU1722460, CYMU1722476 OBOL: WMBW035033 HBOL:SHAADL170415</p>	
Actions Taken	The cargo exams team and owner have been notified of the presence of asbestos.	
Actions Required	Relevant goods will be seized and subject to immediate disposal Hygienist to be consulted regarding deconstruction and disposal of goods. Enforcement Command to be consulted regarding post detection treatment.	
Case Reference/ID or Incident Number	TRIM:OPF2018/198 FID: AC3EWAAAP NIS: 20468211 BIMS: 31115-2018	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector Customs Compliance QLD Phone: (07) §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: Supervisor Customs Compliance QLD Phone: (07) §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	

Drafted by	Name: s22(1)(a)(ii) Position: Senior Border Force Officer Customs Compliance QLD Phone: (07) s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au
Cleared by	Name: s22(1)(a)(ii) Position: Ag Commander Customs Compliance Phone: 02 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au

Purpose	s47E(d)	Detection of undeclared asbestos
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	12JAN2018
	This report	15JAN2018
Location	Goods are currently at: s47E(d)	
Summary	<p>On 30SEP2017, a consignment of goods, including a 1977 Kawasaki motorcycle, was imported from Sweden. s47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the rear brake pads.</p> <p>Consignment details: Importer: s47F Consignor: s47F FID: AC3C7KTAF Container: TGHU8147124 OBL: 961284001</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized s47E(d) CCB to consider s47E(d) 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> BIMS: xxxx-2018 NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Drafted by	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Cleared by	Name: s22(1)(a)(ii) Position: A/g Superintendent National Compliance Program Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	

Purpose	s47E(d)	Confirmation of the presence of reported asbestos
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	10JAN2018
	This report	17JAN2018
Location	Goods are currently at the following s77G premise: s47E(d) [REDACTED]	
Summary	<p>On 7JAN2018, an LCL consignment of four motor vehicles, being one (1) x 1974 MAZDA RX3, one (1) x 1975 MAZDA RX2, one (1) x 1980 MAZDA 323 and one (1) x 1971 MAZDA RX2 was imported by s47F from s47F.</p> <p>s47E(d) [REDACTED]</p> <p>The importer was directed to arrange testing. On 10JAN2018 a hygienist examined the goods and took eight (8) samples of brake pads (one (1) front and one (1) rear from each vehicle for testing.</p> <p>On 11JAN2018, test results were received stating 'Chrysotile asbestos detected' in the following samples:</p> <p>1975 MAZDA RX2 – front brake pad 1980 MAZDA 323 - front brake pad 1971 MAZDA RX2 - front & rear brake pad</p> <p>Sixteen (16) brake pads to be seized.</p> <p>Consignment Details:</p> <p>Consignee: s47F Consignor: s47F Container #: BSIU9853172 OBOL: HLCUAKL171003973 HBOL: 46101535</p>	
Actions Taken	s.206 disposal direction issued by DGM Second QM issued for removal of all brake pads for destruction by licensed asbestos removal company. Enforcement Command consulted in relation to post detection action.	
Actions Required	CCB to consider INS action. Relevant goods to be seized	
Case Reference/ID or Incident Number	TRIM: OPF2018/602 NIS Record ID: 20471583 FID: AC3JNRGEM DGMS Number: N0471039 BIMS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: Position: Phone: Email:	s22(1)(a)(ii) A/g Inspector Customs Compliance NSW +61 2 s22(1)(a)(ii) s22(1)(a)(ii) abf.gov.au

Alternate Point of Contact	Name: Position: Phone: Email:	§22(1)(a)(ii) Acting Supervisor PCI NSW +61 2 §22(1)(a)(ii) §22(1)(a)(iii) abf.gov.au
Drafted by	Name: Position: Phone: Email:	§22(1)(a)(ii) Acting Supervisor PCI NSW +61 2 §22(1)(a)(ii) §22(1)(a)(iii) abf.gov.au
Cleared by	Name: Position: Phone: Email:	§22(1)(a)(ii) Superintendent National Compliance Program +61 §22(1)(a)(ii) §22(1)(a)(iii) abf.gov.au

Purpose	s47E(d) Confirmation of the presence of reported asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	15JAN2018
	This report	23JAN2018
Location	Goods are currently at the following s77G premise: s47E(d)	
Summary	<p>On 23DEC2017, a LCL consignment of a motor vehicle, being one (1) x 1972 GATSBY MG CONVERTIBLE was imported by s47F from s47F</p> <p>s47E(d)</p> <p>The importer was directed to arrange testing. On 12JAN2018 a hygienist examined the goods and took two (2) samples of brake pads one (1) front and one (1) rear from the vehicle for testing.</p> <p>On 15JAN2018, test results were received stating 'Chrysotile asbestos detected' in both of the above samples.</p> <p>On the 16JAN2018 a further QM was issued to s47G for the purpose of removal (pending).</p> <p>Consignment Details:</p> <p>Consignee: s47F Consignor: s47F Container #: UETU2344265 OBOL: HLCUVAN171107134 HBOL: CAVAN</p>	
Actions Taken	s.206 disposal direction to be issued by DGM Second QM issued for removal of all brake pads for destruction by licensed asbestos removal company. Enforcement Command consulted in relation to post detection action.	
Actions Required	CCB to consider s47E(d). Relevant goods to be seized	
Case Reference/ID or Incident Number	TRIM: OPF2018/808 NIS Record ID: 20474100 FID: AC3NYMLKS DGMS Number: TBA BIMS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: A/g Inspector Customs Compliance NSW Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	

Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Acting Supervisor PCI NSW Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au
Drafted by	Name: s22(1)(a)(ii) Position: Senior ABF Officer PCI NSW Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au
Cleared by	Name: s22(1)(a)(ii) Position: A/g Superintendent National Compliance Program Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au

Purpose	§47E(d) Detection of undeclared asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	24JAN2018
	This report	25JAN2018
Location	Goods are currently at: §47E(d)	
Summary	<p>On 10JAN2018, a consignment of hand tools, including 100 x 12V electric winches, was imported from China. §47E(d)</p> <p>A winch was disassembled and samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in a gasket disc from the inside of the winch.</p> <p>Consignment details: Importer: §47G Consignor: §47G FID: AC3PNJ7NS OBL: WBTA000528</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized §47E(d) CCB to consider §47E(d). 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> BIMS: xxxx-2018 NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations Vic Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Cleared by	Name: §22(1)(a)(ii) Position: A/g Superintendent National Compliance Program Phone: §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	

Purpose	s47E(d) Detection of declared asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	31JAN2018
	This report	31JAN2018
Location	Goods are currently at: s47E(d)	
Summary	<p>On 06JAN2018, a 1947 MG motor vehicle was imported from the US. s47E(d)</p> <p>Several samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the engine exhaust flange gasket.</p> <p>Consignment details: Importer: s47F Consignor: s47G FID: AC3NLLX9N OBL:MSCUOZ188027</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized s47E(d) CCB to consider s47E(d). 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Drafted by	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations Vic Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	
Cleared by	Name: s22(1)(a)(ii) Position: A/g Superintendent National Compliance Program +61 s22(1)(a)(ii) Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au	

Purpose	s47E(d) Detection of Undeclared asbestos
Lead Business Area	Customs Compliance Branch
Schedule of Reporting	First Report
Date-Time Group	Event 30JAN2018
	This report 31JAN2018
Location	Goods are currently at the following s77G premise: s47E(d)
Summary	<p>On 13JAN2018, a LCL consignment of 2 x Motorcycles, being one (1) x 1986 HARLEY DAVIDSON VIN 1HD1EBL41GY119038 and (1) x 1942 HARLEY DAVIDSON MILITARY VIN 42XA1177 was imported by s47F from s47F</p> <p>s47E(d)</p> <p>The importer was directed to arrange testing. On 25JAN2018 a hygienist examined the goods and took four (4) samples of brake pads - one (1) front and one (1) rear from the 1986 Harley Davidson and one (1) front brake pad and one (1) sample from wiring insulation from the 1942 Harley Davidson.</p> <p>On 30JAN2018, test results were received stating 'Chrysotile asbestos detected' in both of the above samples.</p> <p>On the 31JAN2018 a further QM was issued to s47G for the purpose of removal (pending).</p> <p>Consignment Details:</p> <p>Consignee: s47F</p> <p>Consignor: s47G</p> <p>Container #: OOLU6778917</p> <p>OBOL: OOLU2597218300</p> <p>HBOL: LGB0053366</p> <p>The importer has previously has had positive asbestos detections in an importation of 10 motorcycles in June 2017. NIS report no 20472791 / FID ACXHX79MN refer.</p>
Actions Taken	Second QM issued for removal of all ACM for destruction by licensed asbestos removal company.
Actions Required	<p>Relevant goods to be seized</p> <p>Referral to Enforcement Command for post detection action</p> <p>s.206 disposal direction to be issued</p> <p>CCB to consider s47E(d).</p>
Case Reference/ID or Incident Number	<p>TRIM: TBA</p> <p>NIS Record ID: TBA</p>

	FID: AC3NYMLKS DGMS Number: TBA BIMS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector Customs Compliance WA Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: Acting Supervisor PCI WA Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: §22(1)(a)(ii) Phone: Acting Supervisor PCI WA Email: +61 §22(1)(a)(ii) §22(1)(a)(ii) abf.gov.au	
Cleared by	Name: Position: Phone: Email:	

Purpose	§47E(d) Detection of declared asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	02FEB2018
	This report	05FEB2018
Location	Goods are currently at: §47E(d)	
Summary	<p>On 18 JAN 2018, a 1962 LANCIA APPIA 3 SERIES motor vehicle was imported from Italy. §47E(d)</p> <p>Three samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos for the Lancia brake pad..</p> <p>Consignment details: Importer: §47F Consignor: §47F FID: AC3TLHT97 OBL:MSCUVW187461</p>	
Actions Taken	· Enforcement Command consulted regarding post detection action.	
Actions Required	· Relevant goods to be seized · §47E(d) · CCB to consider §47E(d)	
Case Reference/ID or Incident Number	· NIS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: A/g Inspector, Compliance Operations Vic Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) ABF.GOV.AU	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations Vic Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) ABF.GOV.AU	
Drafted by	Name: §22(1)(a)(ii) Position: A/g Inspector, Compliance Operations Vic Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) ABF.GOV.AU	
Cleared by	Name: §22(1)(a)(ii) Position: Superintendent National Compliance Program Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) border.gov.au	

Purpose	Detection of Undeclared Asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	06FEB2018
	This report	06FEB2018
Location	Goods are currently at the following s77G depot: s47E(d) [REDACTED]	
Summary	<p>On 24JAN2018 goods described as '26 UNITS OF USED MOTORCYCLES' and '62 PCS OF USED MOTORCYCLE PARTS' were imported by s47G [REDACTED] from supplier s47G [REDACTED] ex Japan. s47E(d) [REDACTED]</p> <p>The broker stated "...The client advised that any items that may contain asbestos have been removed overseas prior to shipping to Australia...". As no evidence was provided to support this claim QM2408311 was raised for asbestos assessment/testing.</p> <p>On 01FEB2018 QM was action and two (2) samples were taken by the hygienist for asbestos testing.</p> <p>At the time of examination the depot had already unpacked the container. They did not have permission to unpack the container. s33 breach referred to Supply Chain QLD team who advised they will undertake an education visit to the depot in relation to the breach.</p> <p>On 06FEB2018 an asbestos analysis report was received confirming the presence of chrysotile asbestos in the two (2) samples. These samples belonged to the rear brake pads of a Honda CX400 motorcycle frame and a Honda GL700 motorcycle frame.</p> <p>This is the fourth positive asbestos detection for this importer.</p> <p>Consignment Details:</p> <p>Importers Name: s47G [REDACTED] FID # AC3YHACCN Container Number: UETU2214744 Ocean Bill Number: COSU6018937250 House Bill Number: NBR12295558</p> <p>Supplier: s47G [REDACTED]</p>	
Actions Taken	Broker advised to notify depot of the presence of asbestos.	
Actions Required	Relevant goods will be seized; s47E(d) [REDACTED]; Referred to Enforcement Command – Awaiting response; s47E(d) [REDACTED] to be undertaken if Enforcement Command declines referral.	
Case Reference/ID or Incident Number	TRIM: OPF2018/1166 BIMS: NIS: 20479737	

Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name:	s22(1)(a)(ii)
	Position:	Senior Border Force Officer PCI SA
	Phone:	(08) s22(1)(a)(ii)
	Email:	s22(1)(a)(ii) border.gov.au
Alternate Point of Contact	Name:	s22(1)(a)(ii)
	Position:	Supervisor PCI SA
	Phone:	(08) s22(1)(a)(ii)
	Email:	s22(1)(a)(ii) border.gov.au
Drafted by	Name:	s22(1)(a)(ii)
	Position:	Supervisor PCI SA
	Phone:	(08) s22(1)(a)(ii)
	Email:	s22(1)(a)(ii) border.gov.au
Cleared by	Name:	
	Position:	
	Phone:	
	Email:	

Purpose:	Detection of Declared Asbestos	
Lead Business Area	Customs Compliance QLD	
Schedule of Reporting	First Report	
Date-Time Group	Event	06FEB2018
	This Report	07FEB2018
Location	Goods are currently at: §47E(d)	
Summary	<p>On 18JAN2018 a consignment containing 3 vehicles (2 X 1975 MAZDA RX3 and 1X 1973 MAZDA RX2) and vehicle parts ex USA was imported by §47F</p> <p>§47E(d)</p> <p>A hygienist examined the goods and took samples of brake pads from each vehicle for testing. On 06FEB2018 test results were received confirming Chrysotile asbestos in all samples.</p> <p>Consignment Details:</p> <p>Consignee: §47F Consignor: §47G 15501 TEXACO AVE PARAMOUNT 90723 US Cargo Type: FCL Container: TGBU5093505 Ocean Bill of Lading: E144316167 House Bill of Lading: LGB0055168</p>	
Actions Taken	Cargo Operations QLD and Depot advised	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized §47E(d) CCB to consider §47E(d) 	
Case Reference/ID or Incident Number	BIMS: NIS: 20480235 FID: AC3XWNMJ9 TRIM: OPF2018/1374	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector Customs Compliance Queensland Phone: 07 §22(1)(a)(ii) Email: §22(1)(a)(iii) border.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: Supervisor Pre-Clearance Intervention Queensland Phone: 07 §22(1)(a)(ii) Email: §22(1)(a)(iii) border.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Senior Border Force Officer - PCI Qld Phone: 07 §22(1)(a)(ii) Email: §22(1)(a)(iii) border.gov.au	
Cleared by	Name: Position: Phone: Email:	

Purpose	§47E(d) Detection of undeclared asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	26 FEB 2018
	This report	26 FEB 2018
Location	Goods are currently at; §47E(d) §47E(d)	
Summary	<p>On 01 February 2018, a consignment of goods including one 1968 JAGUAR E-TYPE was imported from the United States of America. §47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed Asbestos was found in both the upper and lower heat shield in the engine bay</p> <p>Consignment details: Importer: §47F Consignor: §47F FID: AC3XXNX94 Container: EMU8774164 OBL: W135395241</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized §47E(d) CCB to consider §47E(d) 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: SNR Border Force Officer, Compliance Operations VIC Phone: +61 3 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Snr Border Force Officer Compliance Operations VIC Phone: +61 3 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Cleared by	Name: §22(1)(a)(ii) Position: Superintendent, National Compliance Program +61 2 Phone: §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	

Purpose	Detection of Declared Asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	23JAN2018
	This report	01MAR2018
Location	Asbestos affected part (strip) seized and destroyed	
Summary	<p>On 21JAN2018 ^{s47G} imported an air cargo consignment of 11kg described as <i>"Aircraft spares as per attach"</i>.</p> <p>From the documents received it appears that on 20JAN2018 ^{s47G} emailed the importer stating <i>"...Can we please have more product information on Product ID# ^{s47G} As per invoice this product is made of Asbestos which is prohibited imports and requires import permit..."</i>.</p> <p>On 23JAN2018 importer advised their broker that <i>"...The strip contain Asbestos. Please let me know if you have further questions..."</i> and also <i>"...Is it possible for P/N ^{s47G} to be pulled from shipment and returned to shipper?..."</i>.</p> <p>On 03JAN2018 FID AC3WNRGCE was lodged by ^{s47G} to clear these goods describing subject goods as <i>"cap plug contains asbestos"</i>. ^{s47E(d)} ^{s47G} then sent an email to Regulated Goods NSW stating <i>"...Line 30 contains Asbestos as per confirmation below. Please advise how you want to proceed?..."</i>.</p> <p>Permission was granted by Trade and Goods Operational Policy for the asbestos affected part to be removed and appropriately disposed of without testing. This occurred on the 13FEB2018.</p> <p>Infringement notice to be issued.</p> <p>Consignment Details:</p> <p>Consignee: ^{s47G}</p> <p>Consignor: ^{s47G}</p> <p>IDN: AC3WNRGCE MAWBL: 61850257266 HAWB: 2836522290</p>	
Actions Taken	Asbestos affected part seized and disposed of.	
Actions Required	^{s47E(d)} Infringement notice to be issued	

Case Reference/ID or Incident Number	TRIM: OPF2018/870 BIMS: NIS: 20488852
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Senior Border Force Officer PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Supervisor PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au
Drafted by	Name: s22(1)(a)(ii) Position: Supervisor PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au
Cleared by	Name: Position: Phone: Email:

Purpose	Detection of Declared Asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	07MAR2018
	This report	07MAR2018
Location	s47E(d)	
Summary	<p>On 01FEB2018 s47G imported four brake shoes and eight brake flanges ex Spain from supplier s47G.</p> <p>s47E(d)</p> <p>On 14FEB2018 the supplier provided a statement stating "...this product is Asbestos Free...".</p> <p>This was not accepted as suitable assurance so QM 2419454 raised with samples taken for asbestos testing.</p> <p>On 07MAR2018 an asbestos analysis report was received confirming the presence of chrysotile asbestos in the brake shoe sample.</p> <p>Consignee: s47G</p> <p>Consignor: s47G</p> <p>FID: AC3YMT6R MAWBL: 176 - 85354065 HAWB: 810382822258</p>	
Actions Taken	Depot/ Broker and Importer informed.	
Actions Required	<input type="checkbox"/> s47E(d) <input type="checkbox"/> Asbestos affected parts to be seized and destroyed. <input type="checkbox"/> Infringement notice to be issued.	
Case Reference/ID or Incident Number	TRIM: OPF2018/1318 NIS: 20491178	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Senior Border Force Officer PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Supervisor PCI SA Phone: (08) s22(1)(a)(ii)	

	Email: s22(1)(a)(ii) border.gov.au
Drafted by	Name: s22(1)(a)(ii) Position: Supervisor PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au
Cleared by	Name: Position: Phone: Email:

Purpose	s47E(d) Detection of declared asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	26 MAR 2018
	This report	28 MAR 2018
Location	Goods are currently at; s47E(d)	
Summary	<p>On 24 FEB 2018, a consignment of one 1960 Jawa Motorcycle was imported from Germany. s47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the front brake pads.</p> <p>Consignment details: Importer: s47F Consignor: s47F FID: AC4C4CHP9 Container: GESU6416767 OBL: HLCUHAM180181867</p>	
Actions Taken	· Enforcement Command consulted re post detection action.	
Actions Required	· Relevant goods to be seized · s47E(d) · CCB to consider s47E(d)	
Case Reference/ID or Incident Number	· NIS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	
Drafted by	Name: s22(1)(a)(ii) Position: Senior Officer, Compliance Operations VIC Phone: +61 3 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	
Cleared by	Name: s22(1)(a)(ii) Position: Superintendent, National Compliance Program Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	

Purpose	Detection of Declared Asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	28MAR2018
	This report	29MAR2018
Location	§47E(d)	
Summary	<p>On 14MAR2018 §47F imported a package containing goods described as ACTINOLITE ex Thailand but mined in Pakistan.</p> <p>§47E(d)</p> <p>Actinolite is an asbestos mineral silicate listed within the Regulation 2 definition of asbestos, of the Customs (Prohibited Imports) Regulations 1956. The importation of Actinolite asbestos is prohibited pursuant to Regulation 4C.</p> <p>Goods to be seized and destroyed.</p> <p>Consignee: §47F</p> <p>Consignor: §47G</p> <p>MAWBL: 61854386463 HAWB: 4597141780</p>	
Actions Taken	Depot/ Broker and Importer informed.	
Actions Required	<ul style="list-style-type: none"> • §47E(d) • Asbestos affected parts to be seized and destroyed. • Infringement notice to be considered. 	
Case Reference/ID or Incident Number	TRIM: OPF2018/2667 NIS: 20500918	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: Position: Phone: Email:	§22(1)(a)(ii) Senior Border Force Officer PCI SA (08) §22(1)(a)(ii) §22(1)(a)(ii) border.gov.au
Alternate Point of Contact	Name: Position: Phone: Email:	§22(1)(a)(ii) Supervisor PCI SA (08) §22(1)(a)(ii) §22(1)(a)(ii) border.gov.au
Drafted by	Name: Position: Phone: Email:	§22(1)(a)(ii) Supervisor PCI SA (08) §22(1)(a)(ii) §22(1)(a)(ii) border.gov.au
Cleared by	Name: Position: Phone: Email:	

Purpose	s47E(d) [REDACTED] Detection of undeclared asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	04 APR 2018
	This report	06 APR 2018
Location	Goods are currently at: s47E(d) [REDACTED] [REDACTED] [REDACTED]	
Summary	<p>On 24 March 2018, a consignment containing four Ford Mustangs was imported from the USA. s47E(d) [REDACTED]</p> <p>The broker was unable to provide sufficient assurance that the vehicle did not contain asbestos so testing was arranged.</p> <p>Samples were taken from the four vehicles for asbestos testing. Results confirmed the presence of asbestos in a rear brake pad from one 1969 Ford Mustang.</p> <p>Consignment details: Importer: s47G [REDACTED] Consignor: s47G [REDACTED] FID: AC4HK67TF Container: HASU4398943 OBL: SUDU28003A9NHA1U</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized s47E(d) [REDACTED] CCB to consider s47E(d) [REDACTED]. 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Customs Compliance Branch / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Inspector, Compliance Operations VIC Phone: +61 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] abf.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Supervisor, Compliance Operations VIC Phone: +61 3 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] abf.gov.au	
Drafted by	Name: s22(1)(a)(ii) [REDACTED] Position: Inspector, Compliance Operations VIC Phone: +61 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] abf.gov.au	

Cleared by

Name: s22(1)(a)(ii)
Position: Superintendent, National Compliance Program
Phone: +61 s22(1)(a)(ii)
Email: s22(1)(a)(ii) abf.gov.au

Purpose	DETECTION OF DECLARED ASBESTOS	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	05APR2018
	This report	12APR2018
Location	§47E(d)	
Summary	<p>On 23 March 2018 a 1941 FORD SUPER DELUXE VIN# §47G was imported by §47G ex USA.</p> <p>§47E(d)</p> <p>§47E(d)</p> <p>On 05APR2018 a hygienist examined the goods and took two samples from the rear brake shoes. There were no front brake shoes. The hygienist removed all rear brake shoes for testing.</p> <p>On 05APR2018 test results were received confirming chrysotile asbestos in both samples of the brake shoes.</p> <p>Consignment Details:</p> <p>Consignee: §47G</p> <p>Consignor: §47F</p> <p>Container #: YMLU8510827 (LCL) OBOL: E144317897 HBOL: 7188</p>	
Actions Taken	Exams team and owner notified. Hygienist confirms goods destroyed in testing.	
Actions Required	CCB to consider §47E(d)	
Case Reference/ID or Incident Number	TRIM:OPF2018/3421 FID: AC4KNPAWR NIS: 20504357 BIMS:	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector Customs Compliance QLD Phone: (07) §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: Supervisor Customs Compliance QLD Phone: (07) §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	

Drafted by	Name: s22(1)(a)(ii) Position: Senior Border Force Officer Customs Compliance QLD Phone: (07) s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au
Cleared by	Name: Position: Phone: Email:

Purpose:	Detection of Declared asbestos	
Lead Business Area	Compliance Operations Qld	
Schedule of Reporting	First Report	
Date-Time Group	Event	23APR2018
	This Report	23APR2018
Location	Goods are currently at the following s77G premises: s47E(d) [REDACTED]	
Summary	<p>On 10APR2018 a consignment reported as <i>"Iron Scooter"</i> ex Indonesia was imported by s47F [REDACTED].</p> <p>s47E(d) [REDACTED] FID AC4M9MFJW.</p> <p>A hygienist examined the goods and took two samples (brake pads) for testing. On 23APR2018 test results were received confirming Chrysotile asbestos in both samples.</p> <p>This detection is the first positive asbestos detection for this importer.</p> <p>Consignment Details:</p> <p>Consignee: s47F [REDACTED] Consignor: s47G [REDACTED] Cargo Type: LCL Container: CMAU5345740 Ocean Bill of Lading: GNC0153595 House Bill of Lading: SBBNESGL18030061</p>	
Actions Taken	<ul style="list-style-type: none"> • NIS report written • Sitrep prepared • Cargo Operations advised 	
Actions Required	<input type="checkbox"/> Relevant goods will be seized subject to immediate disposal.	
Case Reference/ID or Incident Number	BIMS: NIS: 20514148 TRIM: OPF2018/4044 FID: AC4M9MFJW	
Branch/Division/ Group Specific Reporting Information	Compliance Operations Qld / Regional Command Qld	
Primary Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Inspector Compliance Operations Queensland Phone: 07 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] border.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Supervisor Pre-Clearance Intervention Queensland Phone: 07 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] border.gov.au	
Drafted by	Name: s22(1)(a)(ii) [REDACTED] Position: Senior Border Force Officer PCI Qld Phone: 07 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] border.gov.au	

Cleared by	Name: Position: Phone: Email:
-------------------	--

Released by Department of Home Affairs
under the *Freedom of Information Act 1982*

Purpose:	Detection of Declared asbestos	
Lead Business Area	Compliance Operations Qld	
Schedule of Reporting	First Report	
Date-Time Group	Event	23APR2018
	This Report	23APR2018
Location	Goods are currently at the following s77G premises: s47E(d) [REDACTED]	
Summary	<p>On 10APR2018 a consignment reported as <i>"Iron Scooter"</i> ex Indonesia was imported by s47F [REDACTED].</p> <p>s47E(d) [REDACTED] FID AC4M9M6MJ.</p> <p>A hygienist examined the goods and took two samples (brake pads) for testing. On 23APR2018 test results were received confirming Chrysotile asbestos in both samples.</p> <p>This detection is the first positive asbestos detection for this importer.</p> <p>Consignment Details:</p> <p>Consignee: s47F [REDACTED] Consignor: s47G [REDACTED] Cargo Type: LCL Container: CMAU5345740 Ocean Bill of Lading: GNC0153595 House Bill of Lading: SBBNESGL18030155</p>	
Actions Taken	<ul style="list-style-type: none"> • NIS report written • Sitrep prepared • Cargo Operations advised 	
Actions Required	<input type="checkbox"/> Relevant goods will be seized subject to immediate disposal.	
Case Reference/ID or Incident Number	BIMS: NIS: 20514127 TRIM: OPF2018/4043 FID: AC4M9M6MJ	
Branch/Division/ Group Specific Reporting Information	Compliance Operations Qld / Regional Command Qld	
Primary Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Inspector Compliance Operations Queensland Phone: 07 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] border.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Supervisor Pre-Clearance Intervention Queensland Phone: 07 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] border.gov.au	
Drafted by	Name: s22(1)(a)(ii) [REDACTED] Position: Senior Border Force Officer PCI Qld Phone: 07 s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(ii) [REDACTED] border.gov.au	

Cleared by	Name: Position: Phone: Email:
-------------------	--

Released by Department of Home Affairs
under the *Freedom of Information Act 1982*

Purpose	s47E(d) Confirmation of the presence of reported asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	22MAR2018
	This report	23MAR2018
Location	Goods are currently at the following s77G premise: s47E(d) [REDACTED]	
Summary	<p>On 9FEB2018, a LCL consignment of a motorcycle, being one (1) x 1965 BSA Lightning was imported by s47F [REDACTED] from Great Britain.</p> <p>s47E(d) [REDACTED]</p> <p>The importer was directed to arrange testing. On 14 MAR 2018 a hygienist examined the goods and took two (2) samples of brake pads one (1) front and one (1) rear from the vehicle for testing.</p> <p>On 22MAR2018, test results were received stating 'Chrysotile asbestos detected' in both of the above samples.</p> <p>On 23MAR2018 a further QM was issued to Brokers s47G [REDACTED] for the purpose of removal.(pending)</p> <p>Consignment Details:</p> <p>Consignee: s47F [REDACTED]</p> <p>Consignor: s47F [REDACTED]</p> <p>Container #: CAIU9635051</p> <p>OBOL: A450302987</p> <p>HBOL: C AR127011</p>	
Actions Taken	s.206 disposal direction to be issued by DGM Second QM issued for removal of all brake pads for destruction by licensed asbestos removal company. Enforcement Command to be consulted in relation to post detection action.	
Actions Required	CCB to consider s47E(d) [REDACTED]. Relevant goods to be seized	
Case Reference/ID or Incident Number	TRIM: OPF2018/2950 NIS Record ID: 20498329 FID: AC4CXG6J9 DGMS Number: TBA BIMS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	

Primary Point of Contact	Name: s22(1)(a)(ii) Position: Inspector Customs Compliance NSW Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Acting Supervisor PCI NSW Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au
Drafted by	Name: s22(1)(a)(ii) Position: Senior ABF Officer PCI NSW Phone: +61 2 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au
Cleared by	Name: s22(1)(a)(ii) Position: Superintendent National Compliance Program Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(ii) abf.gov.au

Purpose	s47E(d)	Detection of undeclared asbestos
Lead Business Area	Port Operations Command – Compliance Operations VIC	
Schedule of Reporting	First Report	
Date-Time Group	Event	30 APR 2018
	This report	01 MAY 2018
Location	Goods are currently at: s47E(d)	
Summary	<p>On 21 APRIL 2018, a consignment of goods, including one 1967 Ford Mustang, was imported from the USA. s47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in front brake pads and from the rear brake shoes.</p> <p>Consignment details: Importer: s47F Consignor: s47F FID: AC4N7MHJP Container: SUDU8995739 OBL: SUDU28003AA2E002</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized s47E(d) POC to consider s47E(d) 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> NIS: TBA 	
Branch/Division/ Group Specific Reporting Information	Port Operations Command / Regional Command VIC/TAS	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Supervisor, Compliance Operations VIC Phone: +61 3 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	
Drafted by	Name: s22(1)(a)(ii) Position: Senior Officer, Compliance Operations VIC Phone: +61 3 s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au	
Cleared by		

Purpose	s47E(d) Detection of undeclared asbestos	
Lead Business Area	Port Operations Command – Compliance Operations VIC	
Schedule of Reporting	First Report	
Date-Time Group	Event	30 APR 2018
	This report	01 MAY 2018
Location	Goods are currently at: s47E(d)	
Summary	<p>On 17 March 2018, a consignment of goods, including one 1930 FORD MODEL A VIN AA3033002 was imported from the USA. s47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the Clutch Lining.</p> <p>Consignment details:</p> <p>Importer: s47F</p> <p>Consignor: s47F</p> <p>FID: AC4FTGFRA</p> <p>Container: HASU4016296</p> <p>OBL: SUDU28003A9LEJF6</p> <p>H/Bill: 3543A</p>	
Actions Taken	<ul style="list-style-type: none"> Enforcement Command consulted regarding post detection action. 	
Actions Required	<ul style="list-style-type: none"> Relevant goods to be seized s47E(d) POC to consider s47E(d) 	
Case Reference/ID or Incident Number	<ul style="list-style-type: none"> NIS: 20518465 	
Branch/Division/ Group Specific Reporting Information	Port Operations Command / Regional Command VIC/TAS	
Primary Point of Contact	<p>Name: s22(1)(a)(ii)</p> <p>Position: Inspector, Compliance Operations VIC</p> <p>Phone: +61 s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) abf.gov.au</p>	
Alternate Point of Contact	<p>Name: s22(1)(a)(ii)</p> <p>Position: Supervisor, Compliance Operations VIC</p> <p>Phone: +61 3 s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) abf.gov.au</p>	
Drafted by	<p>Name: s22(1)(a)(ii)</p> <p>Position: Senior Officer, Compliance Operations VIC</p> <p>Phone: +61 3 s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) abf.gov.au</p>	
Cleared by		

Purpose	DETECTION OF UNDECLARED ASBESTOS	
Lead Business Area	Compliance Operations Qld	
Schedule of Reporting	First Report	
Date-Time Group	Event	04MAY2018
	This report	04MAY2018
Location	Goods are currently at the following s77G premises: s47E(d) [REDACTED]	
Summary	<p>On 22APR2018 a Pre-Fabricated House was imported by s47G [REDACTED] on FID AC4PR9CEE.</p> <p>s47E(d) [REDACTED]</p> <p>s47E(d) [REDACTED]</p> <p>On 03MAY2018 a hygienist examined the goods and took four samples.</p> <p>On 04MAY2018 test results were received confirming chrysotile asbestos in the sample of the wall paneling. The three other samples were negative from the electrical cabling, joint putty and panel filling.</p> <p>Consignment Details:</p> <p>Consignee: s47G [REDACTED]</p> <p>Consignor: s47G [REDACTED]</p> <p>Container #: TCNU2380190 (FCL) OBOL: OOLU2602127470 HBOL: S1803302</p>	
Actions Taken	Exams team and broker notified.	
Actions Required	Relevant goods will be seized subject to immediate disposal. Compliance Operations to consider [REDACTED]	
Case Reference/ID or Incident Number	TRIM: OPJ2018/37501 FID: AC4PR9CEE NIS: 20520485 BIMS:	
Branch/Division/ Group Specific Reporting Information	Compliance Operations Qld / Regional Command Qld	
Primary Point of Contact	Name: s22(1)(a)(ii) [REDACTED] Position: Inspector Compliance Operations QLD Phone: (07) s22(1)(a)(ii) [REDACTED] Email: s22(1)(a)(iii) [REDACTED] abf.gov.au	

Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Supervisor Pre-Clearance Intervention Queensland Phone: (07) s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au
Drafted by	Name: s22(1)(a)(ii) Position: Senior Border Force Officer Compliance Operations QLD Phone: (07) s22(1)(a)(ii) Email: s22(1)(a)(iii) abf.gov.au
Cleared by	Name: Position: Phone: Email:

Purpose:	s47E(d) DETECTION OF UNDECLARED ASBESTOS	
Lead Business Area	Port Operations Command - Pre-Clearance Intervention WA	
Schedule of Reporting	First Report Report updates – as required	
ABOC Action Required	Information Only	
Date-Time Group	Event	18/05/2018
	This Report	21/05/2018 08:30AM
Location	Goods are currently located at: s47E(d)	
Summary	<p>A vehicle - 1950 AC 2 LITRE DH COUPE VIN# EL1354 - entered on FID AC4LAYAFX was referred to the ABF from DAWR for asbestos testing.</p> <p>QM # 2461746 was raised and the vehicle was examined at s47E(d)</p> <p>17 samples were taken for laboratory testing.</p> <p>Testing has confirmed that the following parts contain CHRYSOTILE ASBESTOS –</p> <p>Brakepads Left Rear Wheel</p> <p>Thermostat Housing Gasket</p> <p>Intake Manifold Gasket</p>	
Actions Taken	<p>Vehicle currently held at:</p> <p>s47E(d)</p> <p></p> <p></p>	
Actions Required	<p><input type="checkbox"/> Referral to Enforcement Command for post detection action</p> <p><input type="checkbox"/> Relevant goods to be seized</p> <p><input type="checkbox"/> s47E(d)</p> <p><input type="checkbox"/> s47E(d) to be considered</p>	
Case Reference/ID or Incident Number	<p>Importer - s47F</p> <p>FID # - AC4LAYAFX</p> <p>Container # - FSCU6316680</p> <p>OBOL # - 961949059</p>	
Branch/Division/Group Specific Reporting Information	Port Operations Command / Regional Command WA	

Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Pre Clearance Intervention WA Phone / Mobile: §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Pre Clearance Intervention WA Phone / Mobile: §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au
Drafted by	Name: §22(1)(a)(ii) Position: A/g Supervisor, Pre Clearance Intervention WA Phone / Mobile: §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au
Cleared by	Name: Position: Phone / Mobile: Email:
Distributed to	<SITREP Distribution List>

Purpose	§47E(d) Detection of declared asbestos	
Lead Business Area	Compliance Operations Vic, POC	
Schedule of Reporting	First Report	
Date-Time Group	Event	20 June 2018
	This report	21 June 2018
Location	Goods are currently at: §47E(d) §47E(d) §47E(d)	
Summary	<p>On 31 May 2018, a consignment containing four Fiat Vehicles including one 1965, 3 wheel FIAT, were imported from the Italy. §47E(d)</p> <p>§47E(d)</p> <p>Samples of were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the front and rear brake lining from the 1965, 3 wheel FIAT APE 50.</p> <p>Consignment details: Importer: §47F Consignor: §47F FID: AC49F3PGG Container: MSKU6957090 OBL: 964451609</p>	
Actions Taken	Enforcement Command consulted regarding post detection action.	
Actions Required	Relevant goods to be seized §47E(d) Compliance Operations Vic to consider §47E(d)	
Case Reference/ID or Incident Number	NIS: 20541844	
Branch/Division/ Group Specific Reporting Information	Regional Command ACT/HQ, Port Operations Command	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: +61 3 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Cleared by		

Purpose	§47E(d) Detection of declared asbestos	
Lead Business Area	Compliance Operations Vic, POC	
Schedule of Reporting	First Report	
Date-Time Group	Event	04 JULY 2018
	This report	04 JULY 2018
Location	Goods are currently at: §47E(d) §47E(d)	
Summary	<p>On 21 JUNE 2018, a consignment of goods including one 1970 Lamborghini Minura S was imported from the UK. §47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in a front brake pad.</p> <p>Consignment details: Importer: §47G Consignor: §47G FID: AC6F7GEMS Container: MOFU5865630 OBL: ONEYLIVU07685900</p>	
Actions Taken	Enforcement Command consulted regarding post detection action.	
Actions Required	Relevant asbestos containing material to be seized §47E(d) Compliance Operations Vic to consider §47E(d)	
Case Reference/ID or Incident Number	NIS: tba	
Branch/Division/ Group Specific Reporting Information	Regional Command ACT/HQ, Port Operations Command	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: +61 3 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Cleared by		

Purpose	§47E(d) Detection of undeclared asbestos	
Lead Business Area	Compliance Operations Vic, POC	
Schedule of Reporting	First Report	
Date-Time Group	Event	09 July 2018
	This report	10 July 2018
Location	Goods are currently at: §47E(d)	
Summary	<p>On 14 May 2018, a consignment of goods including one 1969 Mercedes 280 SL Convertible was imported from the USA. §47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in exhaust / air intake gasket. No asbestos was detected in right brake pad.</p> <p>Consignment details: Importer: §47G Consignor: §47G FID: AC4YPMRNM Container: HASU1377340 OBL: SUDU28003AAE2XV0</p>	
Actions Taken	Enforcement Command consulted regarding post detection action.	
Actions Required	Relevant asbestos containing material to be seized. §47E(d) Compliance Operations Vic to consider §47E(d) .	
Case Reference/ID or Incident Number	NIS: tba	
Branch/Division/ Group Specific Reporting Information	Regional Command ACT/HQ, Port Operations Command	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: +61 3 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(ii) abf.gov.au	
Cleared by		

Purpose	s47E(d) Detection of Undeclared Asbestos	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	10JUL2018
	This report	10JUL2018
Location	s47E(d)	
Summary	<p>On 20JUN2018 s47G imported an FCL from Indonesia with goods described as "MAGNESIUM OXIDE, FLO-VIS PLUS, NUT PLUG FINE, DEEPCLEAN".</p> <p>Goods description of 'NUT PLUG' s47E(d). The consignment contains 5,000kg of "NUT PLUG FINE" and 5,000kg of "NUT PLUG MEDIUM".</p> <p>Importer produced the following:</p> <ul style="list-style-type: none">➤ Global QHSE Alert regarding asbestos contaminated nut hulls dated 2014;➤ A Certificate of Quality from s47G stating "This is to confirm and certify that the NUT PLUG (Walnut Shell) is produced in a free Asbestos zone.." and "...does not contain any traces of asbestos...";➤ A Chemical Declaration stating "...5. Do these goods contain asbestos? NO..."; and➤ 2014 testing results stating positive results for cummingtonite. Samples tested could not be linked to the current consignment. <p>None of the above assurances were accepted as sufficient so a QM was raised for testing to be undertaken.</p> <p>On 03JUL2018 a sample (7.2grams) of the nut plug was obtained and forwarded for asbestos analysis. Testing company s47G requested further testing stating "...we took a small sample of the material (approx. 7g) from one bag. When we did the analysis we detected 2 very small fibre bundles similar in optical properties to chrysotile asbestos. As these fibres weren't evenly distributed throughout the sample, it didn't seem consistent with typical asbestos containing products. We realise the ramifications if the material does contain asbestos, so for quality control we would like to take more samples (maybe a few from different pallets) so we can eliminate the possibility of any contamination. ..."</p> <p>Further testing was subsequently conducted on 06JUL2018 when a second sample (50kg) of the nut plug was obtained and forwarded for asbestos analysis.</p> <p>On 10JUL2018 an asbestos analysis report was received confirming the presence of chrysotile asbestos in both of the samples.</p> <p>It appears that only the goods described as "NUT PLUG FINE" have been tested. PCI SA to discuss this with hygienist and assess need for further testing on goods described as "NUT PLUG MEDIUM".</p> <p>Importer has requested further testing by different laboratory s47G who undertook the testing back in 2014.</p> <p>Consignee: s47G</p>	

Released by Department of Home Affairs

	<p>s47G [REDACTED]</p> <p>Consignor: s47G [REDACTED]</p> <p>FID: AC6FF4MGC OBOL: 965151186 HBOL: JKT773708 Supplier ID: CCM7637977M</p>
Actions Taken	Depot/Broker and Importer informed.
Actions Required	<ul style="list-style-type: none"> s47E(d) [REDACTED] Detection referred to EC (Investigations) for their consideration
Case Reference/ID or Incident Number	TRIM: OPF2018/5878 NIS: TBA
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division
Primary Point of Contact	<p>Name: s22(1)(a)(ii) [REDACTED]</p> <p>Position: Senior Border Force Officer PCI SA</p> <p>Phone: (08) s22(1)(a)(ii) [REDACTED]</p> <p>Email: s22(1)(a)(ii) [REDACTED] border.gov.au</p>
Alternate Point of Contact	<p>Name: s22(1)(a)(ii) [REDACTED]</p> <p>Position: Supervisor PCI SA</p> <p>Phone: (08) s22(1)(a)(ii) [REDACTED]</p> <p>Email: s22(1)(a)(ii) [REDACTED] border.gov.au</p>
Drafted by	<p>Name: s22(1)(a)(ii) [REDACTED]</p> <p>Position: Supervisor PCI SA</p> <p>Phone: (08) s22(1)(a)(ii) [REDACTED]</p> <p>Email: s22(1)(a)(ii) [REDACTED] border.gov.au</p>
Cleared by	<p>Name:</p> <p>Position:</p> <p>Phone:</p> <p>Email:</p>

Purpose	Asbestos Detection	
Lead Business Area	Customs Compliance Branch	
Schedule of Reporting	First Report	
Date-Time Group	Event	12JUL2018
	This report	13JUL2018
Location	s47E(d)	
Summary	<p>On 01JUL2018 s47F imported one 1966 Lambretta Scooter LI Series 3 ex Vietnam.</p> <p>s47E(d)</p> <p>Importer stated s47F had taken precautions by removing clutch plate and brake pads. s47F made the assumption that, as the gaskets were new, there would be no asbestos risk. This assurance was not considered as sufficient so QM raised for testing.</p> <p>On 12JUL2018 an asbestos analysis report was received which showed chrysotile asbestos present in five (5) of the seven (7) samples obtained from five different gaskets.</p> <p>Consignee: s47F</p> <p>Consignor: s47G</p> <p>FID: AC6FX7XM9 OBOL: MSCUEK907433 HBOL: VML1806003</p>	
Actions Taken	Depot/ Broker and Importer informed.	
Actions Required	<ul style="list-style-type: none"> Asbestos affected parts to be seized and destroyed. s47E(d) to be considered. 	
Case Reference/ID or Incident Number	TRIM: OPD2018/317287 NIS: TBA	
Branch/Division/ Group Specific Reporting Information	Customs Compliance / Border Management Division	
Primary Point of Contact	Name: s22(1)(a)(ii) Position: Senior Border Force Officer PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) @border.gov.au	
Alternate Point of Contact	Name: s22(1)(a)(ii) Position: Supervisor PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au	

Drafted by	Name: s22(1)(a)(ii) Position: Supervisor PCI SA Phone: (08) s22(1)(a)(ii) Email: s22(1)(a)(ii) border.gov.au
Cleared by	Name: Position: Phone: Email:

Purpose	§47E(d) Detection of undeclared asbestos	
Lead Business Area	Compliance Operations Vic, POC	
Schedule of Reporting	First Report	
Date-Time Group	Event	17 July 2018
	This report	18 July 2018
Location	Goods are currently at: §47E(d)	
Summary	<p>On 31 May 2018, a consignment of goods including one 1969 PORSCHE 912 was imported from the USA. §47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the front right disc pad.</p> <p>Consignment details: Importer: §47F Consignor: §47F FID: AC47YXWFE Container: GESU6253314 OBL: E144320248 H/B : NYC0059070</p>	
Actions Taken	Enforcement Command consulted regarding post detection action.	
Actions Required	Relevant asbestos containing material to be seized. §47E(d) Compliance Operations Vic to consider §47E(d)	
Case Reference/ID or Incident Number	NIS: TBA	
Branch/Division/ Group Specific Reporting Information	Regional Command ACT/HQ, Port Operations Command	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: +61 3 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Drafted by	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Cleared by		

Purpose	§47E(d) Detection of declared asbestos	
Lead Business Area	Compliance Operations VIC, POC	
Schedule of Reporting	First Report	
Date-Time Group	Event	09 JULY 2018
	This report	12 JULY 2018
Location	Goods are currently at; §47E(d) §47E(d)	
Summary	<p>On 21 June 2018, a consignment of goods including one 1968 Ford Mustang was imported from Indonesia. §47E(d)</p> <p>Samples were taken for asbestos testing. Results confirmed the presence of chrysotile asbestos in the Head Gasket and Brake Pad and indicated the possible presence of chrysotile asbestos in the Exhaust Gasket.</p> <p>Consignment details: Importer: §47F Consignor: §47G FID: AC6FXGY34 Container: BEAU4481690 OBL: W135403127 H/B: LGB0059561</p>	
Actions Taken	Enforcement Command consulted regarding post detection action.	
Actions Required	Relevant asbestos containing items/parts to be seized §47E(d) Compliance Operations Vic to consider §47E(d) .	
Case Reference/ID or Incident Number	NIS: TBA	
Branch/Division/ Group Specific Reporting Information	Regional Command ACT/HQ, Port Operations Command	
Primary Point of Contact	Name: §22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Alternate Point of Contact	Name: §22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: +61 §22(1)(a)(ii) Email: §22(1)(a)(iii) abf.gov.au	
Drafted by	Name: Position: Phone: Email:	
Cleared by	Name: Position: Phone: Email:	