

<b>Purpose:</b>	Detection of declared asbestos	
<b>Lead Business Area</b>	s47E(d)	
<b>Schedule of Reporting</b>	First Report	
<b>Date-Time Group</b>	Event	10SEP2018
	This Report	22NOV2018
<b>Location</b>	Goods are currently released to importer (post ACM removal)	
<b>Summary</b>	<p>On 18AUG2018 a consignment reported as "Vespa Scooter" ex Indonesia was imported by s47F.</p> <p>s37(2)(b), s47E(d)</p> <p>A hygienist examined the goods and took two samples (complete brake pads) for testing. On 10SEP2018 test results were received confirming Chrysotile asbestos in both samples.</p> <p>This detection is the first positive asbestos detection for this importer.</p> <p>Consignment Details:</p> <p>s47F</p>	
<b>Actions Taken</b>	<ul style="list-style-type: none"> <li>NIS report written</li> <li>Sitrep prepared</li> <li>Cargo Operations advised</li> </ul>	
<b>Actions Required</b>	<ul style="list-style-type: none"> <li>Relevant goods disposed of by testing organization.</li> </ul>	
<b>Case Reference/ID or Incident Number</b>	BIMS: NIS: 20565396 FID: AC63TGK6H	
<b>Branch/Division/ Group Specific Reporting Information</b>	Compliance Operations Qld / Regional Command Qld	
<b>Primary Point of Contact</b>	Name: s22(1)(a)(ii) Position: Inspector Compliance Operations Queensland Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) @border.gov.au	
<b>Alternate Point of Contact</b>	Name: s22(1)(a)(ii) Position: Supervisor Pre-Clearance Intervention Queensland Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) @border.gov.au	
<b>Drafted by</b>	Name: s22(1)(a)(ii) Position: Senior Border Force Officer PCI Qld Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) @border.gov.au	

<b>Cleared by</b>	Name: Position: Phone: Email:
-------------------	--

Released by Department of Home Affairs  
under the *Freedom of Information Act 1982*

## FOI

## Subject:

FW: SITREP for asbestos detection - s47G FID AC64RYRGF s47E(d)

<b>Purpose</b>	s47E(d) Detection of undeclared asbestos	
<b>Lead Business Area</b>	Compliance Operations Vic, POC	
<b>Schedule of Reporting</b>	First Report	
<b>Date-Time Group</b>	Event	26 August 2018
	This report	14 September 2019
<b>Location</b>	Goods are currently at: s47E(d)	
<b>Summary</b>	<p>On 26 August 2018 , a consignment of goods including 5 Gaskets were imported from China s47E(d)</p> <p>After ABF intervention, the importer/Broker voluntarily disclosed that 5 Gaskets contained asbestos and requested for the Gaskets to be voluntarily disposed. Permission was obtained from TGOP. No samples were taken for asbestos testing.</p> <p>Consignment details: s47G</p>	
<b>Actions Taken</b>	s47E(d) raised and goods taken on a B390 # 009947 for disposal by the removalist.	
<b>Actions Required</b>	s47E(d) Compliance Operations Vic s47E(d) .	
<b>Case Reference/ID or Incident Number</b>	NIS: TBA	
<b>Branch/Division/ Group Specific Reporting Information</b>	Regional Command ACT/HQ, Port Operations Command	
<b>Primary Point of Contact</b>	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) @abf.gov.au	

<b>Alternate Point of Contact</b>	Name: s22(1)(a)(ii) Position: A/g Supervisor, Compliance Operations VIC Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) @abf.gov.au
<b>Drafted by</b>	Name: s22(1)(a)(ii) Position: Inspector, Compliance Operations VIC Phone: s22(1)(a)(ii) Email: s22(1)(a)(ii) @abf.gov.au
<b>Cleared by</b>	

**Incident Details**

<b>Security Classification</b>	<del>Protected</del>	<b>Incident Category</b>	s47E(d)
<b>DTG of Report:</b>	19/09/2018	<b>Incident Title</b>	Importation of vehicle containing Asbestos
<b>DTG of Incident:</b>	28/08/2018 16:56:53	<b>Name</b>	s47E(d) RC NSW - Cargo Intervention result/issue - Importation of vehicle containing Asbestos - 28/08/2018 16:56:53
<b>Reporting Region</b>	RC NSW	<b>Reporting Officer</b>	s22(1)(a)(ii)
<b>Incident Theme</b>	Cargo Intervention result/issue		

**Event Details****Summary**

A vehicle imported from South Africa targeted for Asbestos testing was examined and samples drawn by a Competent Person. Test results stated Chrysolite asbestos was detected.

**Full Incident Narrative**

<b>Purpose</b>	s47E(d) Detection of undeclared asbestos	
<b>Lead Business Area</b>	Compliance Operations NSW, POC	
<b>Schedule of Reporting</b>	First Report	
<b>Date-Time Group</b>	Event	28 August 2018
	This report	19 September 2018
<b>Location</b>	Goods are currently at the following premises; s47E(d)	
<b>Summary</b>	On 27 August 2018, an FCL consignment of one (1) x 1947 HUDSON COMMODORE SIX COUPE VIN s47F was imported by s47F Ex. South Africa  s47E(d)  On 11 September 2018, a Competent Person examined the vehicle and took seven (7) samples from various locations for testing.  On 18 September 2018, test results were received stating 'Chrysotile asbestos detected' in the following locations:	

	<ul style="list-style-type: none"> <li>- Passenger side floor pan and fire wall</li> <li>- Underside of vehicle chassis</li> <li>- Exhaust header pipe</li> <li>- Connecting exhaust pipe</li> <li>- Radiator return pipe</li> <li>- Exhaust manifold</li> </ul> <p>Presumed ACM was also suspected in the fly-wheel and clutch plate assembly.</p> <p>Consignment details:</p> <p>s47F</p> 	
<b>Actions Taken</b>	s47E(d) raised and goods sampled and tested.	
<b>Actions Required</b>	<p>Removal and disposal of parts found to contain asbestos to be arranged through licensed asbestos removalist.</p> <p>Compliance Operations NSW s47E(d).</p>	
<b>Case Reference/ID or Incident Number</b>	<p>TRIM: OPF 2018/9529</p> <p>NIS: 20573679</p>	
<b>Branch/Division/ Group Specific Reporting Information</b>	Regional Command ACT/HQ, Port Operations Command	
<b>Primary Point of Contact</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Inspector Customs Compliance NSW</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>	
<b>Alternate Point of Contact</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: A/g Supervisor Customs Compliance NSW</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>	
<b>Drafted by</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Senior Border Force Officer</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>	

## Incident Details

<b>Security Classification</b>	Unclassified	<b>Incident Category</b>	s47E(d)
<b>DTG of Report:</b>	03/10/2018 14:03:52	<b>Incident Title</b>	Positive Asbestos detection in CHEVROLET vehicles FID AC66X7FPK
<b>DTG of Incident:</b>	29/08/2018 14:04:00	<b>Name</b>	s47E(d) - RC NSW - Compliance result/issue - Positive Asbestos detection in CHEVROLET vehicles FID AC66X7FPK - 29/08/2018 14:04:00
<b>Reporting Region</b>	RC NSW	<b>Reporting Officer</b>	s22(1)(a)(ii)
<b>Incident Theme</b>	Compliance result/issue		

## Event Details

## Summary

On 01 September 2018, an FCL consignment of one (1) x 1957 CHEVROLET - VIN s47F and one (1) 1970 CHEVROLET VIN s47F was imported by s47F, Ex. USA. On 25 September 2018, test results were received stating 'Chrysotile asbestos detected'.

## Full Incident Narrative

Purpose	s47E(d) - Detection of undeclared asbestos		
Lead Business Area	Compliance Operations NSW, POC		
Schedule of Reporting	First Report		
Date-Time Group	Event	25 September 2018	
	This report	3 October 2018	
Location	Goods are currently at the following premises;  s47E(d)		
Summary	On 01 September 2018, an FCL consignment of one (1) x 1957 CHEVROLET - VIN s47F and one (1) 1970 CHEVROLET VIN s47F was imported by s47F, Ex. USA.  s47E(d)  On 14 September 2018, a Competent Person examined the vehicles and took two (2) representative samples from a brake calliper of each vehicle.		

	<p>On 25 September 2018, test results were received stating 'Chrysotile asbestos detected' in the following locations:</p> <ul style="list-style-type: none"> <li>- Brake pad of 1957 Light Blue Chevrolet</li> <li>- Brake pad of 1970 Plum Chevrolet Ute</li> </ul> <p>Consignment details:</p> <p>s47F</p> 	
<b>Actions Taken</b>	Goods sampled and tested.	
<b>Actions Required</b>	<p>Section 206 Disposal Direction.</p> <p>Removal and disposal of parts found to contain asbestos by licensed asbestos removalist.</p> <p>Compliance Operations NSW s47E(d) .</p>	
<b>Case Reference/ID or Incident Number</b>	<p>NIS: 20577449</p> <p>TRIM: OPF2018/9828</p>	
<b>Branch/Division/ Group Specific Reporting Information</b>	Regional Command ACT/HQ, Port Operations Command	
<b>Primary Point of Contact</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Inspector Customs Compliance NSW</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>	
<b>Alternate Point of Contact</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: A/g Supervisor Customs Compliance NSW</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>	
<b>Drafted by</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Senior Border Force Officer</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>	
<b>Cleared by</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Inspector Customs Compliance NSW</p>	



**Incident Details**

<b>Security Classification</b>	For Official Use Only	<b>Incident Category</b>	s47E(d)
<b>DTG of Report:</b>	03/10/2018	<b>Incident Title</b>	Positive Asbestos detection - 1966 Dodge Dart - FID AC66YFA3T
<b>DTG of Incident:</b>	01/09/2018 00:00:00	<b>Name</b>	s47E(d) - RC NSW - Compliance result/issue - Positive Asbestos detection - 1966 Dodge Dart - FID AC66YFA3T - 01/09/2018 00:00:00
<b>Reporting Region</b>	RC NSW	<b>Reporting Officer</b>	s22(1)(a)(ii)
<b>Incident Theme</b>	Compliance result/issue		

**Event Details****Summary**

On 01 September 2018, an FCL consignment of one (1) x 1966 DODGE DART VIN s47F and one (1) x 1971 DODGE Pickup VIN s47F was imported by s47F, Ex. USA.

On 25 September 2018, test results were received stating 'Chrysotile asbestos detected' in the following location:

- Brake pad of Cream Dodge Dart

**Full Incident Narrative**

<b>Purpose</b>	s47E(d) Detection of undeclared asbestos	
<b>Lead Business Area</b>	Compliance Operations NSW, POC	
<b>Schedule of Reporting</b>	First Report	
<b>Date-Time Group</b>	Event	29 August 2018
	This report	3 October 2018
<b>Location</b>	Goods are currently at the following premises;  s47E(d)	
<b>Summary</b>	On 01 September 2018, an FCL consignment of one (1) x 1966 DODGE DART VIN s47F and one (1) x 1971 DODGE Pickup VIN s47F was imported by s47F, Ex. USA.  s47E(d)	

Released by Department of Home Affairs  
under the Freedom of Information Act 1982

	<p>On 14 September 2018, a Competent Person examined the vehicles and took two (2) representative samples from a brake calliper of each vehicle.</p> <p>On 25 September 2018, test results were received stating 'Chrysotile asbestos detected' in the following location:</p> <ul style="list-style-type: none"> <li>• - Brake pad of Cream Dodge Dart</li> <li>•</li> </ul> <p>Consignment details:</p> <p>§47F</p> <div style="background-color: #cccccc; width: 400px; height: 100px; margin-top: 5px;"></div>		
<b>Actions Taken</b>	Goods sampled and tested.		
<b>Actions Required</b>	<p>Section 206 Disposal Direction</p> <p>Removal and disposal of parts found to contain asbestos by licensed asbestos removalist</p> <p>Compliance Operations NSW §47E(d)</p>		
<b>Case Reference/ID or Incident Number</b>	<p>NIS: 20577533</p> <p>TRIM: OPF2018/9833</p>		
<b>Branch/Division/ Group Specific Reporting Information</b>	Regional Command ACT/HQ, Port Operations Command		
<b>Primary Point of Contact</b>	<p>Name:</p> <p>Position:</p> <p>Phone:</p> <p>Email:</p>	<p>§22(1)(a)(ii)</p> <p>Inspector Customs Compliance NSW</p> <p>§22(1)(a)(ii)</p> <p>§22(1)(a)(ii) @abf.gov.au</p>	
<b>Alternate Point of Contact</b>	<p>Name:</p> <p>Position:</p> <p>Phone:</p> <p>Email:</p>	<p>§22(1)(a)(ii)</p> <p>A/g Supervisor Customs Compliance NSW</p> <p>§22(1)(a)(ii)</p> <p>§22(1)(a)(ii) @abf.gov.au</p>	
<b>Drafted by</b>	<p>Name:</p> <p>Position:</p> <p>Phone:</p> <p>Email:</p>	<p>§22(1)(a)(ii)</p> <p>Senior Border Force Officer</p> <p>§22(1)(a)(ii)</p> <p>§22(1)(a)(ii) @abf.gov.au</p>	

**Incident Details**

<b>Security Classification</b>	For Official Use Only	<b>Incident Category</b>	s47E(d)
<b>DTG of Report:</b>	26/09/2018	<b>Incident Title</b>	s47E(d) Customs Operations WA - Asbestos Detection - 25SEP2018
<b>DTG of Incident:</b>	25/09/2018 12:26:15	<b>Name</b>	s47E(d) RC WA - Cargo Intervention result/issue - Pre- Clearance Intervention - Customs Operations WA - Asbestos Detection - 25SEP2018 - 25/09/2018 12:26:15
<b>Reporting Region</b>	RC WA	<b>Reporting Officer</b>	s22(1)(a)(ii)
<b>Incident Theme</b>	Cargo Intervention result/issue		

**Event Details****Summary**


s47E(d) Customs Operations WA - Asbestos Intervention - 25SEP2018

**Full Incident Narrative**

SITREP:

<b>Purpose</b>	s47E(d) Detection of undeclared asbestos	
<b>Lead Business Area</b>	Pre-Clearance Intervention, Compliance Operations WA, POC	
<b>Schedule of Reporting</b>	First Report	
<b>Date-Time Group</b>	Event	25 September 2018
	This report	26 September 2018
<b>Location</b>	Goods are currently located at the following premises; s47E(d)	
<b>Summary</b>	On the 10th September 2018 an FCL consignment containing one (1) Ford 5 Window Coupe (Project) 1933 – VIN s47F was imported by s47F ex South Africa. s47E(d) On the 18th September 2018 a Competent Person examined the vehicle and took ten (10) samples from various locations on the vehicle for asbestos testing. On 25th September 2018, test results were received stating 'Chrysotile asbestos detected' in the	

 Released by Department of Home Affairs  
under the Freedom of Information Act 1982

	<p>following locations:</p> <ul style="list-style-type: none"> <li>• Gasket to redundant pipe of exhaust</li> <li>• Black resin block in Brake pads</li> <li>• Red fibrous gasket to the engine</li> <li>• Green fibrous gasket to the engine</li> </ul> <p>Consignment Details:</p> <p>s47F</p> 
<b>Actions Taken</b>	s47E(d) raised and goods sampled and tested.
<b>Actions Required</b>	<p>Removal and disposal of parts found to contain asbestos to be arranged through licensed asbestos removalist.</p> <p>Compliance Operations WA s47E(d).</p>
<b>Case Reference/ID or Incident Number</b>	<p>TRIM: OPF2018/9729</p> <p>NIS: 20575946</p>
<b>Branch/Division/ Group Specific Reporting Information</b>	Regional Command ACT/HQ, Port Operations Command
<b>Primary Point of Contact</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Inspector Customs Compliance WA</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>
<b>Alternate Point of Contact</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: A/g Supervisor Customs Compliance WA</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>
<b>Drafted by</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Senior Border Force Officer</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>
<b>Cleared by</b>	<p>Name: s22(1)(a)(ii)</p> <p>Position: Inspector Customs Compliance WA</p> <p>Phone: s22(1)(a)(ii)</p> <p>Email: s22(1)(a)(ii) @abf.gov.au</p>